

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/18/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155472		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 5300 W 96TH ST B. WING _____		(X3) DATE SURVEY COMPLETED 08/29/2012	
NAME OF PROVIDER OR SUPPLIER HOOSIER VILLAGE				STREET ADDRESS, CITY, STATE, ZIP CODE 9875 CHERRYLEAF DR INDIANAPOLIS, IN 46268			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K 000	<p>INITIAL COMMENTS</p> <p>A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health.</p> <p>Survey Date: 08/29/12</p> <p>Facility Number: 000548 Provider Number: 155472 AIM Number: NA</p> <p>Surveyor: Mark Caraher, Life Safety Code Specialist</p> <p>At this Quality Assurance Walk-thru survey, Hoosier Village was found in compliance with 410 IAC 16.2-3.1-19(ff).</p> <p>This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection hard wired to the fire alarm system in resident sleeping rooms, support rooms and at smoke barrier and horizontal exit doors. The facility has a capacity of 122 and had a census of 67 at the time of this survey.</p> <p>The facility was found in compliance with state law in regard to sprinkler coverage and was found in compliance with the state law in regard to smoke detector coverage.</p> <p>All areas where residents have customary access were sprinklered. The facility has no detached buildings providing facility services.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 09/04/12.</p>			K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/18/2012
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155472		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - 5300 W 96TH ST B. WING _____		(X3) DATE SURVEY COMPLETED 08/29/2012	
NAME OF PROVIDER OR SUPPLIER HOOSIER VILLAGE				STREET ADDRESS, CITY, STATE, ZIP CODE 9875 CHERRYLEAF DR INDIANAPOLIS, IN 46268			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE